


S.S. "ST.JESSICA"

With reference to the conclusion on Page 3 of the endorsement dated 12th January, 1949, Mr.Stocks, after consulting with the local Surveyors, confirms that the repaired bower anchor is now in an efficient condition and does not require to be re-tested and that they are satisfied the Society's requirements have been complied with as regards the 30 fathoms of chain cable placed on board at Greenock in July 1943.

This assurance was obtained over the telephone yesterday.

  
29.1.49



© 2021

Lloyd's Register  
Foundation

003065-003074-0243