

T.



# LLOYD'S REGISTER OF SHIPPING

Salvage Association Buildings,  
Clarence Road, Cardiff

Telephone : 32481 & 32482 Cardiff

Telegrams : Register, Cardiff

Reference

RECEIVED  
- 5 MAY 1958

Enclosures.

3rd May, 1958

Dear Sir,

"EAGLESDALE".

The above vessel is undergoing Special Survey at this port, in connection with this we enclose herewith a list of thicknesses as ascertained by drilling and would be pleased to receive your approval of these at your earliest convenience.

With reference to drill tests in deck in way of No.1 cargo tank, one plate in C.strake port was found to be .40" and has been recommended for renewal but the Admiralty Overseer in charge states that he is not prepared to renew or double this plate. Further drill tests in the plate concerned gauged .39" and .45"

The Overseer states that the vessel is due to be sold or broken up in two years time and no repair should be carried out to the plate at this Special Survey.

The First Entry Report, Midship Section, Profile and Deck and Shell Expansion plans are also enclosed and should be returned with your reply.

Yours faithfully,  
The Surveyors,

per :-

*James D. J. Key*

*D 1124*

The Secretary,  
LONDON.



© 2020

Lloyd's Register  
Foundation

003075-003082-0151

SR.

CLASSIFICATION

H

M

1/8 off 1/4 SS

REQUESTING EARLY

the thickness of this plate is considered  
adequate until the next Special Survey.  
It is therefore submitted that the S.S notation  
be now assigned but that the Dr notation  
be withheld until the plate is renewed as now  
recommended by the Cardiff Surveyors *GH* 7.5.58



© 2020

Lloyd's Register  
Foundation

Clarence Road, Cardiff

Salvage Association Buildings

LLOYD'S REGISTER OF SHIPPING

210 11 1958

RECEIVED

1958