

211 SEP 1952

SHIP'S NAME "THEODOXUS" REPORT Rot. No. 47866
VC

Outstanding Conditions of Class: SUBJECT to indented keel plating
amidships being kept under observation at
successive drydockings,

S.R.L. Appendix. (~~As before~~ or None)

Nature of Present Survey: (~~As before~~ and in dry dock)

Docking; Permanent/Deferred wear and tear repairs
to rudder pintle etc., E.W. repairs to lower end of
sternframe; Examination of deferred items as above.

Recommendation:

SUBMITTED record of 'DS 8.59' be assigned, SUBJECT
as above, and to lower end of sternframe (E.W. 8.59)
being specially examined next drydocking and to top
rudder pintle etc. being permanently repaired before
ship is recommissioned.

C.S.S. Records Dept.

DS 8.59. SUBJECT.

to note.

OFFICE NOTE

Sternframe repairs.

Structure reinforced - Cff. 1.53

Docking brackets fitted - Cff. 11.55

NOTE:

Ship is stated to be laid up at an Irish port.