

Im. 8. 31.



F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Se Sr SILVERELM*

Rpt. *Sld*

No. *28808*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long.
Transverse No. *13616*

Depth "d" *24.13*

Framing: Table No. *14*

Description *Channel frame as approved*

2nd Longitudinal No. *33232*

Proportions Length = *10.32*
Depth =

Deck Sheerstrake *as approved*

This vessel has been built in accordance with the Revised Rules and the Builders have obtained the owners sanction thereto.

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A.1. (Steel)** "with freeboard," as recommended. The Summer freeboard of *3ft 5 1/2 ins.* from centre of disc to top of statutory deck line at - deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Strs (stl)

Cell D.B. '322' 971t, D.Tf25'976t, F.P.T 140t, A.P.T 220t.

F.K, Duet Keel forward 127', 7B.H. (Col B.H. to weather 5k), pt cems, *Lloyds A.C.P.*

It is concluded that the fore-castle beams as shown in the report are bulk angles, but the Surveyors should be requested to state if this is so.

F. 30'

Lloyd's Register Foundation

0200-501890-001800