

Class is subject to

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

29 JAN 1962

SHIP'S NAME.....

"CAPE PALLISER".....

REPORT.....

HUL.....

No.67340.

MBS due 2.62. Now held.

Docking. Tailshaft seen.

ES due 1.62 and postponement until 12.62 approved 21.11.61 provided a satisfactory General Examination held and the Surveyor states the machinery now generally examined and found or placed in good condition.

The Surveyor states the Main Engine crankshaft MP pinion found slack and the crankshaft now re-built.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of MBS 11.61 and TS (CL) 11.61, and it is further submitted that the proposal to postpone the ES merits the favourable consideration of the Committee.



© 2020

Lloyd's Register  
Foundation

26.1.62.



003106-003115-0261