

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Overseas: Committee, London, E.C.3

2nd August, 1962

Telephone: ROYal 9166  
Telex No.: 24305

Dear Sirs,

m.s. "BRITISH PROGRESS"

The Society's Surveyors at Dublin have reported that this ship was under survey last month when temporary repairs were carried out to two main engine tie bolts which had been found to be fractured at the bottom of the threads.

It was recommended that the main engine tie bolts between cylinder units numbers 1 and 2, starboard side, and numbers 5 and 6, port side, should be renewed by January 1963 and the Committee have continued the class subject to these matters receiving attention by that time.

Yours faithfully,

Deputy Clerk to the  
Classification Committee

The B.P. Tanker Co. Ltd.,  
Britannic House,  
Finsbury Circus,  
London, E.C.2



© 2020

Lloyd's Register  
Foundation

003116 - 003123 - 0052

003116 - 003123 - 0051