

Lloyd's Register of Shipping.

UNITED WITH THE BRITISH CORPORATION REGISTER

Prins Hendrikkade 159,

AMSTERDAM 3rd June, 1957

4 - JUN 1957

AM DISTRICT.

ns to be addressed to-
RVEYORS.

Reference

Dear Sir, *Ans'd*

m.s. "CAPELLA" Ams Report No. 21298

reference

CL/AR

With reference to our letter CL/IK dd. 22nd May, 1957 we can inform you that we received the following answer from the Owner of the m.s. "CAPELLA" (M.J.Rusthoven, Botanicuslaan 1, HAREN.Gr.):

" The Chief engineer is informed by me that the
"mainengine must not be continuously operated at
" 318 RPM, to mark the tachometer with red at 318 RPM
" and about the notice board which has to be fitted. "

Yours faithfully,

Pro Surveyors,

The Secretary,
LONDON

J. Remel

E 27.3.



© 2020

Lloyd's Register
Foundation

003124-003130-0042

CLASSIFICATION

CLASSIFICATION

The Surgeon should be requested
to advise this office when the notice
board has been felted at the United
States & meanwhile the Complaint
Certificate will be forthwith

444.
19/6/57

© 2020

Lloyd's Register
Foundation

