

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

26 FEB 1938

VESSEL'S NAME _____

"JAMES ROCKBREAKER"

Report _____

Lon. _____

No. 103496

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

When due _____

The Boiler Survey became due 9,37.

In reply to enquiry [as to what arrangements^{ARE PROPOSED} for the carrying out of the Boiler Survey due 9,37,] the Port Natal Surveyor states that the Owners do not wish to retain the classification of this vessel.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Handwritten signatures and date:
 24.2.38
[Signature]
[Signature]



© 2020

Lloyd's Register
Foundation

003138-003146-0065