

COPY

LLOYD'S REGISTER OF SHIPPING,

H U L L.

3rd July, 1946.

Dear Sir,

In reply to the enquiry contained in your classing letter of the 28th June regarding the case of the "INO" our report No.53468, we beg to state that a stringer 12" x 3/8" thick, flanged 6" on the face is fitted all round the O.F. bunker space at a height of 8'-0" above the D.B. tank top.

This also applies to the sister vessel "CATO", our report No.53546.

The dynamo test certificates for both vessels have been forwarded today.

We are, Dear Sir,  
Yours faithfully,  
per the Surveyors.

(Sgd.) Leslie Storey.

The Secretary,  
LONDON.



Lloyd's Register  
Foundation

003154-003161-0158

CO 104-100-100

For Ship Surveyors (F.E.Rpts.) to note. /c.D  
For Engineer Surveyors (F.E.Rpts.) to note. J.R.

COPIES OF REPORTS

L I D H  
SHEL, INT. INC.

COPY



© 2020

Lloyd's Register  
Foundation

FRAM  
SIDE  
Fram  
Rev  
Dep  
Fram  
Dian  
State  
Are  
Pe  
are  
of  
th  
NGL  
Floo  
Mid