

This vessel is undergoing extensive alterations having

"WOODESSE" 1919.

WRECK
SECTION
No. 785

(Not in R.B. after 1955/6. Presumed broken up 22.5.63)

WRECK
SECTION
No. 785

RETAIN
LR

© 2020

Lloyd's Register
Foundation

003162-003174-0001

Stringers

Have Ventilators and their Coamings been examined

Timbers of Frame at openings