

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

London

Port of Istanbul


30th January, 1959.

This is to Certify that I have

ved the S.S. "IMROZ" 1125 tons gross of Istanbul on
in January 1959 and subsequently, whilst the ship lay
in Iskenderun Harbour on account of damage stated to
been caused by blast and fire due to the M.T. "MIRADOR"
ing whilst the ship was moored alongside on the 13th
1959 at Iskenderun,

that I have transmitted to the Committee of Lloyd's
of Shipping, London, a Report stating that all repairs
ended by me have been completed to my satisfaction, and
have Recommended that she be retained as now
in the Register Book without fresh record of
subject to the ship being towed direct to Istanbul
docking and permanent repairs.


to carry



Surveyor to Lloyd's Register.

John M. Taylor

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
Surveyors, or other Officers or Agents of the Society."



003162-003174-0152