

2 - JAN 1963

's name "ERNEBANK"

Port

YKA.

No.

4479

The ship is subject to shell plates D.8 & 9 (p.s) and C.10 (s.s) (grooved and temporarily repaired) being specially examined and dealt with as necessary by the S.S., to shell plate (holed) in No.8 D.B. tank being examined and dealt with as necessary next drydocking, to bulwark stiffeners at forward end of shelter deck and stiffeners at forward and after hatch coamings being dealt with by 12,62, also to 15 fathoms of chain cable being supplied at the earliest opportunity.

ACTION is DEFERRED for Special Survey by 12,62, also for examination in dry dock after grounding.

The year of grace expired 6,62.


A SPECIAL SURVEY (D) became due 6,61 and was postponed until 9,62. The Owners now request further postponement until 1,63 in order to proceed to the Continent where the ship may be sold for scrap. This proposal was accepted 20.1.62 subject to the ship being generally examined and found or placed in a satisfactory condition for the proposed voyage to Europe.

The YOKOHAMA Surveyors report ship examined afloat and found in satisfactory condition for the proposed voyage. Temporary repairs were also carried out as well as wear and tear repairs.

In view of the above, IT IS SUBMITTED ACTION be DEFERRED for Special Survey by 1,63, and for examination in dry dock after grounding, SUBJECT to shell plates D.8 & 9 (p.s) and C.10 (s.s) (grooved and temporarily repaired) being specially examined and dealt with as necessary by the Special Survey and to shell plate (holed) in No.8 D.B. tank being examined and dealt with as necessary next drydocking, to bulwark stiffeners at forward end of shelter deck and stiffeners at forward and after hatch coamings being dealt with by 1,63, and to holed shell plate in No.8 D.B. tank being renewed by 1,63, also to 15 fathoms of chain cable being supplied at the earliest opportunity.

SUBJECT
AMENDED.

IN S.R.L.
Drydocking (grounding).



© 2020

Lloyd's Register
Foundation