

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10 When handed in at Local Office 10 Port of London

No. in Survey held at Reg. Book 26642 on the Wood, Iron or Steel "Sc." Leha Date, First Survey Last Survey 19

TONNAGE: GROSS 1599, UNDER DK. 1367, NET 973. Built at Bowes By whom J.S. White & Co. Ltd. When 1922 11. Owners D/S A/S Laly Managers C.T. Gogstad & Co. Owners' Address (if not already recorded in Appendix to Register Book). Port belonging to Oslo.

WRECK SECTION No. 275

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

WB=CellDBorDBa feet; uE&B feet; f feet } total capacity tons. FPT tons; APT tons; MT feet tons. N.B.—All alterations in the existing records should be underlined.

CHARACTER	Years Assigned now or expired	Machinery and Boiler Surveys (including date of N.B., if any)
+100 A.I.S. 30.		+LMC
S.S. mdb. 1-26.		B.S. 430
		M.S. 8.26.
		C.L. 6.29.

Last Report, No. 17718 Port Ant. Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Summary of Damage Repairs :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

General Condition of the	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
ing of Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
ngs	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Bats
& Fastenings	Ceiling	Scuppers	Msts, Yards, &c.
e Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained (state if wedges removed)
hooks	Rudder	Hatches	Sails
ms	Steering gear and its connections	Planking of Wood Vessels	Equipment letter
e Frames	Windlass	Caulking ditto	Anchors, No. of
adinals	Have Pumps now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)
erces	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	" length (on board) size
is	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crumples ditto	" Rule length size
rs	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
ottom Plating		Ditto Ditto at other places ditto	Standing and Running Rigging
		Stringers, Clamps & Shelves ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Fee (per Section 20)	Damage or Repair Fee (if any) (per Sec. 20)	Lighting Expenses (if chargeable)	Surveyor's Fee (if any)	Fees applied for	Received by me
£	£	£	£	19	19

TUE. 8 MAR 1932

Surveyor to Lloyd's Register of Shipping. General Committee, Thursday, 31st December 1931. Classing Committee's decision confirmed.

Committee's Minutes Character Assigned Withdraw Class & insert Write own 20 31/12/31

003181-003190-0188

Is Certificate required? If so, to be sent to