

# COPY

## LLOYD'S REGISTER OF SHIPPING

3268



MS "TWEEDBANK"

Port

This Certificate  
Accompanies

**YOKOHAMA**

**REPORT**

No. 3268

Dated 14-6-60

25th May, 1960

This is to Certify that I have

Surveyed the Machinery of the H.V. "TWEEDBANK" 5627 tons gross of BELFAST, on the 17th May, 1960 and subsequently whilst the vessel lay in Drydock at YOKOHAMA for DAMAGE (1):- stated due to fouling turning Buoy in Port de Galets, REUNION, on the 17th February, 1960; (2) stated due to vessel grounding and consequent refloating in 200 fms. on the 12th April, 1960 and that I will transmit to the Committee of Lloyd's Register of

Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book, subject to edges of propeller blades (p & s) being faired and tips dressed as necessary at next drydocking; subject also to all items at present attached to vessel's class being dealt with as previously recommended.

Parts now examined:  
(C.S. Items only)


*J. Winn.*  
Engineer Surveyor to Lloyd's Register.  
J. Winn

### KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS (CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS (OG)	Tailshaft Survey—Oil Cland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 1,60 KOB



0571-05190-0280