

23 MAY 1961

SHIPS NAME "STAD SCHIEDAM" REPORT Rot. No. 51387

GB

Outstanding Conditions of Class: SUBJECT to sternframe  
 (E.W. 2,59 and previously) (slightly fractured at oster)  
 and to indented shell plates G.15 and H.14 (p.s.) in way of No.4  
 hold and indented bottom shell plates D.4,5 & 6 (s.s.f) being  
 specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (As before ~~or None~~)Nature of Present Survey: (~~As above~~ in dry dock)

Drydocking: Examination of deferred items as above: Wear and  
 tear repairs: Damage - shell plate B.4 (s.s.f) indented (cause unknown)

Recommendation:

SUBMITTED record of 'DS 3,61' be assigned as  
 recommended, subject as above, and to shell plate  
 B 4 (s.s.f) being specially examined and dealt  
 with as necessary next drydocking.


DS 3,61 Subject.

IN S.R.L. APPENDIX.

Shell plates (p.s.f) indented.

IT IS FURTHER SUBMITTED the Surveyors be requested  
 to confirm whether the overboard discharges and scuppers, steering  
 gear (main & aux.) and windlass were examined at this time.

C.S.S. Records Dept.  
 to note.



© 2020  
 Lloyd's Register  
 Foundation