

THROUGH HELSINGFORS

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

28th August, 1958.

Dear Sirs,

Steamer "TURID"

Classn (S)

AH/CB

This ship was under survey at Aalborg last month, when the Society's Surveyors examined repairs which had been carried out to the main condensers. The repaired tube plates were found to be satisfactory, and the condensers were tested hydraulically, and found to be tight. It was recommended, however, that the main condenser tube plates should be re-examined by the end of July, 1959, and the Committee have continued the class subject to this being done by that time.

The class of the ship is subject also to indented shell plates Nos. 4 and 14 in the first strake below the sheerstrake, port side forward, being examined and dealt with as necessary at the next Special Survey.

In the meantime a record of Drydocking 7,58, together with notations of Screwshaft Survey 7,58 and Main Boiler Survey 7,58 have been assigned.

Yours faithfully,

c.c.Hfs.

Clerk to the
Classification Committee.

Messrs. Carsten B. Danielsen & Sons,
Shellmangatan 19,
HELSINGFORS.



Lloyd's Register
Foundation