

The Class is subject to the tube plates of the Main Condenser being specially examined and dealt with as necessary before the vessel is placed in commission.

4E

Vessel has recently been laid up.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "TURID"

REPORT ABQ No. 17695

MBS due 1.57 now held.

Locking Screwshaft examined.

Ch.

Repairs to main Condenser now specially examined.

Repaired Tube Plates found satisfactory and Condenser tested hydraulically and found tight.

The Surveyor recommends that the main Condenser tube plates be re-examined before the end of July 1959 (12 months limit)

It is submitted that this vessel is eligible to remain as **CLASSED**.

with full records of MBS, 7.58 and TS (Ch) 7.58 now subject as now recommended.

Lloyd's Register  
Foundation

20.8.58