

18 SEP 1931

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel Sc.K. "BERYL II"

Report \_\_\_\_\_

Ton. \_\_\_\_\_

No. 96680a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

The Sydney Surveyors forward a letter from the Owners as follows:—

"We see no reason why we should continue this vessel in class  
"as we are not likely to sell. Accordingly, we have decided to  
"discontinue class".

It is submitted the class of the vessel be withdrawn from  
the Register Book and three dots (...) inserted in lieu, indicating  
withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2020

 Lloyd's Register  
 Foundation  
 17.9.31