

subject to

✓ These stopped tubes in exhaust gas section of ~~main~~  
D. boiler being renewed on ship's arrival at a convenient home port. 4E

and of Damaged electrical circuits for cargo lighting, being repaired  
on ship's arrival at a convenient home port.

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

119 APR 1961

S NAME

M.V. TARONGA

REPORT

Oslo

No. 9251.

Damage (fire) repairs.

§ Rk. Item (2) above (electrical circuits) was dealt with and  
to be deleted.



It is submitted that this  
vessel is eligible to remain  
as **CLASSED**, subject as above re D. boiler tubes and  
without condition re electrical circuits.

126

NB Re D.B. record see ~~entry~~ of 22/2/61.



© 2020

Lloyd's Register  
Foundation

003217-003222-0148