

191 MAR 1938

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

"DARTMOUTH".

Report

Lon.

No.

103506a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____


When due _____

The Screw shaft Survey became due 11,37.

In reply to enquiry the Halifax Surveyor forwards a copy of a letter received from the Owners, from which it appears that they have decided to take the vessel out of class.

It is submitted the class of this vessel be withdrawn from the Society's Register Book and Three Dots(...) inserted in lieu thereof, indicating withdrawal of class at Owners' requested.

Withdraw class
Insert ...



© 2020

Lloyd's Register
Foundation

10.3.38.

003217-003222-0196