


T.E.S. "TRIGONOSEMUS"  
T.2. Tanker  
-----

The Owners' letter of the 3rd February with reference to the Liverpool Surveyors' recommendation that the cargo and stripping pump motor controls should be removed from their present location was discussed by the undersigned with Mr. Logan this afternoon. It was explained that this was not a new requirement but has been a requirement of the Rules since 1939.

Mr. Logan eventually agreed to move the controls to a safe position at the next convenient opportunity.



16th February, 1949.



© 2020

Lloyd's Register  
Foundation

003240-003244-0153