

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9163

2nd January, 1959.

Classn(S)

AH/EME Dear Sir,

Steamer "EMPIRE SHEARWATER"

With reference to Glasgow report No. 89407, I shall be glad if you will draw the attention of the Surveyors to the Secretary's letter reference Eng. of the 3rd October, 1958, and let me know whether items 1, 3, 5, 6 and 7 in the Rpt. 9 have been complied with as these are not mentioned in the report.

It is concluded that the reported thicknesses of deck plating drilled at the 1st strake inboard, port and starboard forward, 4th strake inboard, port and starboard forward, 2nd strake, port side aft, and 5th strake, port side aft, are not indicative of the general thickness of the plating, but confirmation of this is desired.

Please also furnish the particulars of the overall length of the ship as that reported would appear to be incorrect.

Yours faithfully,

pro Clerk to the
Classification Committee.

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

003245-003251-0152