

F.E.

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME *Steel S.S. "ARGO"*Rpt. *Rot*No. *11690*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Transverse No. *56.75*Depth "d" *17.1*Framing: Table No. *3*Description *Bulb angle as approved*Longitudinal No. *13336*Proportions Length = *8.54*
Depth =*Bridge Deck Sheerstrake as approved.*

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100.A.1. (*Steel*)
1 Dk (*Steel*) "Well Dk"

Cell *JB* 182 355t FPT.14t, APT 31tFK, ABH, Cam, Rly as A.C.P. *P.B. 187' F 23'*

the 2nd Deck in No 2 Hold has not been fitted, webs are fitted in End Space
Concluded the thickness of the Side Girders are as approved and that the
Surveys have Satisfied themselves regarding the fitting of the Material as stated in Secretary's Letter M dated 2.3.21
1-4-21

003252-003262-0142

© 2020

Lloyd's Register
Foundation