

# MONTREAL OFFICE

Name:-

KEYDON

Report No.

Mtl. 12567

Signature of Survey:-

EXAMINATION OF STRUCTURE IN WAY OF DB TANKS

The following remains to complete the survey:-

Defective internal structure in way of DB tanks to be dealt with as necessary before the vessel is again placed in service.

Recommendations:-

The Vessel appears eligible to remain as classed <sup>with</sup> without fresh record of Survey, subject as above.

Insert in S.R.L.

*[Handwritten signature]*

© 2020

Lloyd's Register  
Foundation

*[Handwritten signature]*  
January 30th, 1959.

2510-182500-512500