

Chief Surveyors 19.7.17
12.7.17

Received from Chief Surveyors _____

L'S NAME Shells Maikar

Report GR No. 17155

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

f Survey 1st Enly - When due _____

❖ 100A-1. Steel,
2 Strs (Steel) 3" Dr. (Steel) in hot. Hold.
Cell DB 414. 1615E D.T. a 37' 1234C F.P.T. 100C a.P.T. 96C
FK. T.B.H. Cen. Lys. are. P.47. B126 F47

M
19.7.17

It is concluded ^{that} the upper deck plating is of the thickness required ^{but} the Surveyors should state if this is so as this information has been omitted from their report ^{see}.

M



© 2020

Lloyd's Register Foundation

1120-68250-28700