


s.s. "EMPIRE MIRANDA"

GLASGOW REPORT NO.67058

Glasgow Report recommends a temperature test being carried out on the Generator at a reduced rating. They should be asked what arrangements, if any, they have made with a view to this temperature test being carried out. They should also state why the test was not carried out before the ship left the Builders hands, in view of the difficulty of obtaining such tests subsequently.

*It is submitted the installation is eligible for
Class. without special notation.*

21.5.45.



Lloyd's Register
Foundation

003298-003306-0272