

Mr. Watson

Empire Miranda

I enclose the report on this vessel  
as it contains a recommendation by the  
Surveyors which does not seem to have  
been carried out - yet. Will this  
require a special sanction to be placed  
on the vessel's class? Dynamometer certificate  
also enclosed.



© 2020

20/5/43.

Lloyd's Register  
Foundation

003298-003306-0273

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME Portisham REPORT Lis No. 368  
Nottingham 32

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

*Oil Engines 4 S.C.S.A.*  
*7 Cy. 12 1/2" - 15"*

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of



© 2020

Lloyd's Register  
Foundation