

4E

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

17 SEP 1959

P'S NAME.....TETELA

REPORT.....Kgn

No. 6014

Class expunged with notation "to be broken up" has been
entered against the ship's name in the Register Book.

Damage repairs effected to main engine
M.P. Slide valve.

IT IS SUBMITTED this vessel is eligible to
remain as classed.