

# REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 17-6- 19 59 When handed in at Local Office Kingston 19 59 Port of MONTREAL  
 No. in Reg. Book 67196 Survey held at Kingston Date, First Survey & Last Survey 14-4- 19 59  
 (No. of Visits ONE)

on the Steel S.S. "KEYNOR"  
 TONNAGE:—  
 GROSS 1806 Built at Londonderry By whom N. of Ireland S.B. Co. Ltd. When 1914 6  
 UNDER DK. 1090 Owners La Verendrye Line Limited  
 NET 1090 Managers \_\_\_\_\_ Port belonging to Montreal

Surveyed Afloat or in Dry Dock? Afloat Name of Dock \_\_\_\_\_ Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 12014 Port Mtl

REPAIRS, OR EXAMINATION AS PER RULE FOR LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
*100A1 with fbd. For service on the River St. Lawrence & Great Lakes also on the Gulf of St. Lawrence 1st April to 30th November.	*LMC 4,57 BS M 2,58 TS(GL) 11,56 s.p.s. 2,55
S.S. (Dr) 9,48 Lake	4,57
A.S.	4,58

ITEMS EXAMINED AND CONDITION FOUND, ETC.	
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	Good
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes		Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Renewal Survey been held?	Yes		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

**General Observations, Opinion as to Class, Recommendation, Etc.:**

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, 1,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,59.

Survey Fee \$ 36.00  
 Special Damage or Repair Fee (if any) U.S.S.A. \$ 4.00  
 Travelling Expenses \$ 20.00  
 Second Surveyor's Fee (if any) \$ \_\_\_\_\_  
 Fees applied for, JUN 18, 1959

Committee's Minute THURSDAY - 9 JUL 1959

Character Assigned AS 4,59  
MBS 2,59

*A. K. McDougall*  
 Surveyor to Lloyd's Register of Shipping.



Noted for Header

If so, is the Report sent now, or when will it be sent?

NOW