

"E L E N I"

Before this case receives the consideration of the Committee, it is submitted the Surveyors be informed that the chain cables also require to be ranged and gauged for the Modified Special Survey. Their comments are invited.

They should further be requested to advise whether the present survey is for 3 months only to be followed by another complete Special Survey in 5,63 or if subject to certain repairs, the full S.S. 2,63 can then be granted. If the latter is the case a list of outstanding repairs for full S.S. Notation should be furnished.

It would appear that they have inadvertently recommended record of DS and Notation of Mod.S.S. of 2,62 instead of 2,63.

See

W. J. C. 15/3/63

*W. J. C.
15/3/63*



© 2020

Lloyd's Register
Foundation

003328-003332-0065