

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

keep pd.

VESSEL'S NAME Steel Screw "NAHOON" Report Gls. No. 56559

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____ First Entry _____ When due _____ --

*100A1

1 Dk.

Cell. DB 112', 191t, FPT 63t, APT 46t.


FK, 3 BH, Cem. Lloyd's A & CP.

Q 106', B 13', F 34'

Machy. aft.

Note for Office Use:

Bolted door in bulkhead between hold and bunkers to be riveted on arrival of ship Durban - Durban (P.Nl.) Surveyor's report to be awaited.


 © 2020 *36* 
 Lloyd's Register
 Foundation
 003328-003332-0167