

Surveyor

Received from Chief Ship Surveyor

23 FEB 1948

"TENAGODUS"

REPORT

Lis.

No. 4488

Requests of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Statement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement. — Extract from Sub-Committee's Report, 24/5/42.

This vessel holds the notations 100A1 "Carrying Petroleum in Bulk" (Classification Contemplated) and "Examined 9.47" with record of docking survey 9.47.

The class is subject to indented shell plating (p & s) being dealt with at the first convenient opportunity and to equipment being brought up to the Rule requirements at the first opportunity.

A Periodical Special Survey (B) for Classification has been commenced.

TO COMPLETE S.S: See Liverpool Report No. 126099.

The LISBON Surveyors report 1.48 this Tanker afloat and a bower anchor and 120 fathoms of chain cable missing. It appears that this vessel now has 150 fathoms of chain cable on board (Rule requirements 330 fathoms).

It is submitted ACTION be DEFERRED for equipment.

See subsequent arrangements made at P.Sol.

© 2020

Lloyd's Register
Foundation

003328-003332-0230