

m,4,59

4E

18 JUN 1959

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

TENAGODUS

Nwc

No. 116176

SHIP'S NAME.....

REPORT.....

The Surveyor reports some damage sustained to propeller and one blade found cracked in way of previous repairs. The vessel is proceeding to lie up for an indefinite period and the Surveyor recommends that the class be made subject to the propeller being dealt with as necessary before the vessel returns to service.

IT IS SUBMITTED this vessel is eligible to remain as classed subject as recommended.

gn
5.6.59



© 2020

Lloyd's Register
Foundation

003328-003326269