

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

GB

SHIP'S NAME "CATALINA S"

REPORT Miami

No. 396

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey.....

Examination afloat after  
grounding.

When due.....

Had this case been dealt with in this Office ACTION would have been DEFERRED for examination in dry dock after grounding.

INSERT IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX.

Side shell plating (p &amp; s) slightly indented and wavy.

The Surveyors state this ship was sold prior to completion of present survey but the new Owner is unknown.



© 2020

Lloyd's Register  
Foundation

003333-003340-0092