

1

Sent to Chief Surveyors

Received from Chief Surveyors

31 OCT 1938

VESSEL'S NAME "SIMPSON" Report Lon. No. 103658

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

When due

The 2nd S.S.No. **2** became due 9,38.

The Owners' have recently written, (see correspondence attached) intimating their decision to withdraw the class of this trawler from the Society's Register Book.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

[Handwritten signature]
[Handwritten signature]
 29.10.38



© 2021

Lloyd's Register
Foundation

003341-003348-0106