

ved by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME *Stl & M.V. "MONTE PIANA"* Rpt. *2i* No. *7237*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

1st Long
Transverse No. *11133*

Depth "d" *16.395*

Framing: Table No. _____ Description *Built angle frames as approved*

2nd Longitudinal No. *32333*

Proportions Length *14.37*
Depth = _____

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed



✦ 100 A.1. (Steel).


2 D^o (Stl).

Cell D.B. 334 1116t, D.T.a 52' 1000t, F.P.T. 94t, A.P.T. 86.t

F.K, 8 B.H. (1 B.H to 2nd D^o), pt cm, Lloyd's A.C.P.

P 34', B 261', F 44'.

[Signature]
13.8.26



The Surveyor should be requested to state whether the frames and, revised frames in way of the bracket floors are built ^{with} angles as approved and to forward particulars of the stream wire.

003357-003368-0182