

Received from Chief Ship Surveyor.....

SHIP'S NAME "KADERBAKSH" REPORT Chg. No. 116

Outstanding Conditions of Class:

For conditions of class see previous  
Endorsement.

ACTION is DEFERRED for a Special Survey by 3,61 18 AUG 1961

R.L. Appendix. (~~As before~~ or None)

Surveys due: A SPECIAL SURVEY (D) became due 3,61 but postponement until  
3,62 was approved 2.5.61.

Structure of Present Survey: (Afloat and ~~in dry dock~~)

Temporary repairs on account of leakage in way of fore peak tank (p & s).

Special Features:

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: 3,62.

Recommendation:

SUBJECT to buckled frames in way of No.2 hold (p.s.a),  
bunker hatch lower coaming and both hawse pipes being  
specially examined and dealt with as necessary/also to  
inner bottom plating in way of No.2 D.B.tank and shell  
plate G.1 (s.s.f) being examined and dealt with by the  
Special Survey, to 45 fathoms of chain cable being supplied  
at the earliest opportunity and to No.2 hold port bilge and  
sounding pipe being examined and dealt with and to the  
fore peak tank being pressure tested by 9,61, but ACTION  
be DEFERRED for a Special Survey by 3,62 and for Repairs.

SUBJECT  
AMENDED.



© 2020

Lloyd's Register  
Foundation

003377-003384-0131