

Lloyd's Register of Shipping.  
SURVEYS FOR FREEBOARD.—STEAM SHIPS.

REMARKS RELATING TO ALL STEAM SHIPS EITHER FLUSH DECKED, OR WITH  
PLANT FORECASTLES, SHORT POOPS AND BRIDGE HOUSES DISCONNECTED, OR  
WITH TOP GALLANT FORECASTLES HAVING LONG POOPS, OR RAISED QUARTER DECKS  
CONNECTED WITH BRIDGE HOUSES, OR OTHERWISE.

Port of Survey

Date of Survey

Name of Surveyor

Ship's Name.	Port of Registry and Nationality.	Official Number.	Gross Tonnage.	Date of Build.	Particulars of Classification.
CYPRIAN PRINCE	British Newcastle	142842		1919	+ 100 A-1.
Number in Register Book					

LENGTH.	BREADTH.	DEPTH.	UNDER DECK TONNAGE.
331.3	46.8	23.2	2831.29
330-625	Frame Depth <sup>10</sup> Rule " 5 1/2	Ceiling + .20 Sheer + 1.00	Peak Tanks
330.625	46.05	24.40	2831.39

Moulded Depth as measured..... 25'-6"

NOTE. — If the depth is measured when vessel is afloat, the details of measurement should be reported.

Addition for Keel below base line  
for draught record....**2 1/2**...inches.

CORRECTION FOR LENGTH.

Length of Ship on Loadline.....	330.625	
Length in Table .....	306.00	
Difference .....	24.625	
Correction for 10ft., Table A. ....	1.3	Table C. .7
× Difference divided by 10 .....	3.20	(if required.) 1.72
If $\frac{6}{10}$ ths length covered divide by 2	3 $\frac{1}{4}$	+ 1 $\frac{3}{4}$

CORRECTION FOR IRON DECK.

Proportion covered, if less than $\frac{1}{16}$ ths length covered .....	-48	
Thickness of usual wood deck, less stringer .....	3½	-13½

CORRECTION FOR ROUND OF BEAM.

Breadth at Gunwale amidships.....	46.5
Round of Beam .....	12
Normal round.....	11 3/4
Difference .....	1/4 ÷ 2 = .....
Proportion of Deck uncovered (Para. 19) .....	

NOTE. — The round of beam should be reported on the full breadth of vessel at the gunwale.

Freeboard, Table A .....	5 - 7 <sup>3</sup> / <sub>4</sub>
Correction for Sheer .....	- 9
	4 - 10 <sup>3</sup> / <sub>4</sub>
Correction for Length .....	3 <sup>1</sup> / <sub>4</sub>
	5 - 2
Allowance for Deck Erections .....	- 8 <sup>1</sup> / <sub>2</sub>
	4 - 5 <sup>1</sup> / <sub>2</sub>
Correction for Round of Beam.....	✓
Correction for fall in Sheer (if any).....	✓
Correction for Steel Deck (if required) .....	13 <sup>1</sup> / <sub>4</sub>
	4 - 3 <sup>3</sup> / <sub>4</sub>
Additions for non-compliance with provisions of { ..... }	✓
Para. 11 (d) and (e) ‡	
Other Corrections (if any) .....	✓

Winter Freeboard .....		4-4
Summer Freeboard .....	-4 1/4	3-11 3/4
Indian Summer Freeboard .....	-4 1/4	3-7 1/2
N. A. Winter Freeboard .....		

Correction necessary because clearside amidships, measured in accordance with the Statute is not taken at the intersection of the wood or steel deck with side.

Winter Freeboard from deck line	.....
Summer       "       "       "       "	.....
Indian Summer       "       "       "	.....
N. A. Winter       "       "       "       "	.....

SUMMER FREEBOARD amidships from Centre of Disc to top of Deck Line, <del>Wood</del> Steel, Deck:—	
Tropical Fresh Water Line above Centre of Disc	... 10 1/2 ...
Fresh Water Line	... 6 ...
Tropical Line	... 4 1/2 ...
Winter Line below	... 4 ...
Winter North Atlantic Line	... 4 ...

Tropical Fresh Water Freeboard ...	
Fresh Water	... 37 ...
Tropical	... 37 ...
Winter	... 37 ...
Winter North Atlantic	... 37 ...

MAY 1932

Corresponding percentage { 31.04 %  
(Para. 11, 12, 13, or 14)

8 APR 1932  
Also for Mr. S. J. Hill to 701

3 APR 1932

8  
\$1.80 for Jan

77 - MAY 1932

003377-603384-0163

RECEIVED 31/10/40 MARKING FORM 15 AUG 1936 RECEIVED

sh Water Freeboard ...  
...  
...  
...  
Atlantic ...

RECEIVED  
19-5-60  
18/6/51

Lloyds Register Foundation