

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee London Telex
Telex No.: 24305

Telephone: ROYal 9166

10th July, 1959.

Dear Sirs,

Steamer "TWEED"

sn.(S)

/SJD

This ship was under survey at Montevideo in May/June when a crack in the after main feed pump water end valve chest was repaired by the Metalock process.

It is recommended, however, that these repairs should be re-examined by the end of December, 1959, and the Committee have continued the class subject to this matter receiving attention by that time, and to the propeller being examined or renewed at the next dry docking.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Superintendent Engineer,
Royal Mail Lines Ltd.,
Royal Mail House,
Leadenhall Street,
London E.C.3.



© 2020

Lloyd's Register
Foundation

003371-003884-0175