

2m, 9, 18.

Chief Ship Surveyor 29. 11. 18

Received from Chief Ship Surveyor

NAME Stl. S.S. "No. 2".

Rpt. Gl.s. No. 38323

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

Survey

The Glasgow Surveyors should be requested to state whether it is to be understood that this vessel has been completed as a Hopper in accordance with the originally approved plans and has not been altered for the carriage of oil fuel in bulk as shown on the amended plan which they also forwarded ~~here~~.

L. Ges. 30th

M

29. 11. 18



© 2020

Lloyd's Register
Foundation

003391-003400-0223

BEAMS, Third and Fourth Deck, Single Angle,

Bulb Angle, Plate, Tee Bulb, or Channel

Angle on ditto