

16 OCT 1959

Received from Chief Ship Surveyor

SHIP'S NAME "MEMLING" REPORT B.As. No. 30743

Standing Conditions of Class: SUBJECT to No.4 'tween deck  
insulation in way of No.7 D.B.tank air pipe (s.s.) being repaired  
prior to loading refrigerated cargo.

1. Appendix. (As before ~~or None~~)

2. Particulars of Present Survey: (Afloat ~~and in dry dock~~)

Wear and tear repairs.

Recommendation:

SUBMITTED the ship is eligible to remain  
as classed, but without special condition.


As Now. Without.

IN S.R.L. APPENDIX.

Indents in a few shell plates (p & s).

NOTE:- Subject <sup>item</sup> stated dealt with at B.As. (See Rpt.No.29934 and  
Endorsement dated 10.12.58).

14/10/59



© 2020

Lloyd's Register  
Foundation