

"FRANSINE CLORE" (ex. Fort Winnebago). T. 2. Tanker.

Before this case receives consideration the reply to the Secretary's letter of the 18th Dec. addressed to Mr. Bennett regarding the equipment of chain cable on the "GRAVENCHON" is awaited.

see letter from Mr. Bennett.
15.1.48. re "GRAVENCHON".

15.
2.2.48.



© 2021

1-1-48.

Lloyd's Register
Foundation

003409-003416-0260

lower half affecting slightly the edge of adjacent C stroke plates.
Shell plates D-5 set up slightly at forward end over area 2'x3".

(a) grounding, and so far as could be seen no damage appears to have been sustained. The Surveyor however recommends that

It is submitted



© 2021

Lloyd's Register
Foundation