

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

V'S NAME "FRANCINE CLORE"

REPORT

Adn. 1173  
Lon. No. 116313

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This case is fully stated in an endorsement dated 19. 12. 47.

To complete the Classification Survey the items detailed in Jacksonville Report No.1356 require to be dealt with. Also First Entry reports should be prepared and forwarded for record purposes as opportunity arises.

The Aden Surveyor reports the renewal of a number of defective tubes in the starboard boiler; and the London Surveyors report an examination in dry dock and examination of the windlass.

IT IS SUBMITTED action be deferred pending completion of the Classification Survey.

  
7. 5. 48.



© 2021

Lloyd's Register  
Foundation

003409-003416-0292