

EA

COPY

Ship's name

"IRINI'S BLESSING"

Port

VEN.

No. 0830

The class is subject to stem and stem plating etc. forecastle side plating and side shell plating etc. in way of No.4 hold (p.s) being specially examined and dealt with as necessary by the Special Survey, also to the side shell plating, storm valve and pipe in way of No.5 hold (p.s) being specially examined and dealt with as necessary, also to No.3 hatch beams in way of boat deck being replaced by March '63.

63

37

26

ACTION is DEFERRED for Special Survey.

A SPECIAL SURVEY (D) became due 3,62. Postponement until 10,62 was approved 4.6.62 - G.E. held 4,62. A further postponement until 3,63 was approved 11.10.62 subject to the condition of class being re-examined and found satisfactory for desired postponement. Messrs.F. Wigham Richardson & Co.Ltd., in answer to an enquiry were advised by letter dated 18.1.63 that the Society's minimum requirements for maintenance of this ship's class to enable the ship to proceed to Hong Kong for arrival in April/May next, it would be necessary for the ship to be drydocked and a G.E. held so that the ship may be found or placed in a satisfactory condition for the postponement desired. Special Attention being given to items Nos.1 & 2 of the Society's letter of 17.12.62.

The VENICE Surveyors report (3,63) ship examined in dry dock and the requirements of a G.E. for extension of class up to 3,63 - refer Committee's cable dated 14.3.63, carried out. Minor wear and tear repairs were also effected. All the deferred items as above specially examined and considered satisfactory for the proposed voyage to Hong Kong.

The year of grace expires 3,63.

IT IS SUBMITTED ship is eligible to have record of DS 3,63 assigned, subject to stem and stem plating etc., forecastle side plating and side shell plating etc. in way of No.4 hold (p.s) being specially examined and dealt with as necessary by the Special Survey, also to side shell plating, storm valve and pipe in way of No.5 hold (p.s) being specially examined and dealt with as necessary, also to No.3 hatch beams in way of boat deck being replaced by 3,63, but further ACTION continues to be DEFERRED for Special Survey.

DS 3,63 Subject amended.

IN S.S.L. APPENDIX

Indents in tank top plate No.4 hold (p.s.f).  
Indented shell plates (p & s).

IF IS FURTHER SUBMITTED postponement of the class until 5,63 i.e. until ship's arrival at Hong Kong from which voyage merits the favourable consideration of the Committee.

End. S.3

END. S.3

© 2020



Lloyd's Register  
Foundation

02 3.63 July 1963