

MONTREAL OFFICE

STARMOUNT

Report No.

Mtl. 13463

Survey:-

Part MBS

Vessel laid up.

Work remains to complete the survey:-
ete Boiler Survey.

Safety valves to be adjusted under steam

Conditions:-

The Vessel appears eligible to remain as classed ~~without~~ with
s complete, as above.

with
without fresh record of MBS 2,60 when the Survey



© 2020

Lloyd's Register
Foundation

June 11th, 1960

003429-003433-0052