

4E

Subject to

forward turbo feed pump being repaired by 5/61.

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

13 JUN 1961

NAME ss. "E880 PORTFLEET" REPORT Southampton No. 26833

Repairs

✓ 26856

SKL. The above item dealt with by renewal of rotor shaft and to be deleted.

It is submitted that this vessel is eligible to remain
 as **CLASSED** without condition.

13/6/61 L



© 2020

Lloyd's Register
Foundation

003434-003443-0072