

3 JUN 1951

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB
VESSEL'S NAME 'K Y L O E' REPORT Sld. No. 35567

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to windlass bedplate being renewed by next drydocking.

The SUNDERLAND Surveyors report (4.51), the vessel placed in dry dock, bottom coated, and minor repairs effected.

The existing cross bunker bulkhead removed, and a new bulkhead constructed four frame spaces forward of original, in accordance with approved plan.

The PERIODICAL SPECIAL SURVEY (C), due 4.52, commenced by the examination of the cross bunkers.

In reply to enquiry the Surveyors state in a letter dated 25.5.51 that the windlass bedplate, as above, was renewed.

IT IS SUBMITTED the vessel is eligible to remain as classed, with record of docking survey 4.51, without special condition.

4.51 Sld. Without.

S.S. Part Held.

CARGO BATTENS NOT FITTED.

003434-003443-0340

