

'K Y L O E'

Before this case receives consideration
IT IS SUBMITTED the SUNDERLAND Surveyors be informed
- that the windlass bed plate was recommended by
the NEWCASTLE Surveyors in 3.50 to be renewed
by this drydocking, and requested to state whether
this has been dealt with.

They should also be informed there are
no records in this Office of set up bottom plating.
They should accordingly furnish particulars of the
cause and disposition of the damage now reported.

K



Handwritten signature
11.5.51

Shoys Register
Foundation

003434-003443-0343