

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

19½, P.O. & B.I. Building, York Street
(P.O. Box No. 270), Colombo

Telegrams: Register, Colombo.

Telephone: No. 3694.

P. F. CHESTERS
J. N. JARVIE
SURVEYORS

RECEIVED

7 FEB 1958

3rd February, 1958

Ans'd

Classn. (S)

Dear Sir,


"Starline Merchant"

We are in receipt of your letter dated 7th January, 1958, regarding our report No.4095 on the above vessel. As stated in our reply to your memorandum of the 31st October last, we were informed by the Owners that they intended to carry out the Special Survey of this vessel at Bombay, in December 1957, and that the Boiler and Screwshaft Surveys would be effected at that time. We have since been informed that the vessel is now at Bombay for the above purpose. The damaged shell plating referred to in the above report was not repaired here and it is presumed that this will be dealt with during the course of repairs at Bombay.

Yours faithfully,

The Secretary,
LONDON.

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING



Lloyd's Register
Foundation

003450 - 003457 - 0064

SR

CLASSIFICATION

H

10M

Noted
8.24.8
SPR

4/4/88

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED

UNCLASSIFIED



© 2021

Lloyd's Register
Foundation