

ceiling in Holds, thickness and material

2 1/2 PINE (DOUBLE) UNDER ✓

Cargo Battens, thickness, material and

1 SEP 1948

Port, New York Date August 23rd, 1948

APPLICATION FOR CLASSIFICATION SURVEY.

Please give directions for a Survey to be made on the

"SEA KING"

7210 Tons (Gross) of — (Port)

at Halifax, N.S. for the

purpose of Classification

the vessel will be ready for inspection on now

I hereby undertake to pay the Fees and expenses in connection with the above

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:-

While the Committees of the Society use their best endeavors to ensure that the functions of the Society are properly executed, it is to be understood that the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street,  
London, E.C.3.

Arthur D. S. Egan, Jr. President L.R.C.

Address 17 Battery Place, N.Y.C.

00 3450 - 003451 - 0218

The Steering gear, windlass and bilge suction were examined under working conditions